


Glass Break Sensor



Glass break sensors should be placed opposite of the window being monitored. Ideally, they should be located 4 to 20 feet from your window. They may be placed on a wall, on the ceiling or placed on a shelf.

» Ideally, point the sensor directly at the windows you want protected.

- 1 Remove the backing film.
- 2 Press and hold firmly in place for 30 seconds.

