


Glass Break Sensor



Glass break sensors should be placed opposite of the window being monitored. Ideally, they should be located within 15 feet of your window. They may be placed on a wall, on the ceiling or placed on a shelf.

- 1 Affix the base to the desired location utilizing the long mounting screws with anchors that are provided.
- 2 For wall mounting, the test button should be oriented down towards the floor.
- 3 **IMPORTANT:** When attaching the detector to the base, match the alignment marks and twist clockwise.

Ceiling Placement



Wall Placement

